



SWIMMING POOL/SPA INSPECTION REPORT

FACILITY NAME: ROTARY WATER FEATURE	OWNER NAME: CITY OF LEMOORE	FACILITY ID#: FA0004057	DATE: August 15, 2012
FACILITY SITE ADDRESS: 300 E ST LEMOORE, CA 93245	BUSINESS PHONE: (559) 924-6767	INSPECTION TYPE: ROUTINE INSPECTION	INSPECTOR: Veronica Santa Cruz-REH

An inspection of your facility revealed the following violations of the California Health and Safety Code and/or California Code of Regulations. The violations (if any) noted below must be corrected immediately or as otherwise indicated on the report. A reinspection may occur at any time to verify correction of these violations.

3611 PUBLIC SWIMMING POOL - PR0008934

— Inspection Violations —

ADEQUATE SANITIZER LEVEL NOT MAINTAINED

[T22 CCR 65529]

Inspector Comments: Today, the free available chlorine measured at 0.5 ppm. All interactive water features must measure at 3 ppm of free available chlorine.

General Comments and Observations:

Due to the interactive water feature not having a sufficient amount of chlorine, the water feature was shutdown. The city must submit plans indicating how the system was built so that our department can determine how a commercial type of chlorinator can be installed to the system. The method that the city is currently using to chlorinate the system is not sufficient to ensure the recirculated water is maintained at 3ppm of free available chlorine and between 7.2 -7.8 for the pH

Please submit a copy of the construction plans for the wintertime as soon as possible and do not turn on the water feature until permission to do so has been granted by this department.

If this box is checked the pool/spa was officially closed and posted today because of the violations noted in the report. A follow-up inspection must be conducted by this Department and written approval given prior to reopening the pool. Contact our office at 584-1411 to schedule a reinspection once the violations have been corrected.

Received By:

Veronica Santa Cruz-REHS

Agency Representative